

This rule was filed as Rule G-506.

TITLE 19 NATURAL RESOURCES AND WILDLIFE
CHAPTER 14 GEOTHERMAL POWER
PART 96 ABANDONMENT

19.14.96.1 ISSUING AGENCY: Energy and Minerals Department, Oil Conservation Division, P.O. Box 2088, Santa Fe, New Mexico.
[Recompiled 12/31/01]

19.14.96.2 SCOPE: [RESERVED]
[Recompiled 12/31/01]

19.14.96.3 STATUTORY AUTHORITY: [RESERVED]
[Recompiled 12/31/01]

19.14.96.4 DURATION: [RESERVED]
[Recompiled 12/31/01]

19.14.96.5 EFFECTIVE DATE: [November 15, 1983]
[Recompiled 12/31/01]

19.14.96.6 OBJECTIVE: [RESERVED]
[Recompiled 12/31/01]

19.14.96.7 DEFINITIONS: [RESERVED]
[Recompiled 12/31/01]

19.14.96.8 ABANDONMENT: Injection or disposal wells are required to be abandoned in the same manner as other wells. (See Sec. E, Abandonment, Temporary Abandonment, and Plugging of Wells).
[Recompiled 12/31/01]

HISTORY OF 19.14.96 NMAC:

Pre-NMAC History: The material in this Part was derived from that previously filed with the State Records Center and Archives:

Rule G-506, Abandonment, 11/1/83.

History of Repealed Material: [RESERVED]